




BOSCH

Conettix Universal Dual Path Communicator

B465



en

Release Notes

Table of contents

1	Introduction	4
1.1	Requirements	4
2	Firmware version 2.09	5
2.1	What's new	5
2.1.1	B444-A and B444-V support	5
2.1.2	California Security of Connected Devices Act	5
3	Firmware version 2.08	6
3.1	What's fixed	6
3.1.1	Updates to the bootloader	6
3.1.2	Updates to TCP keep alive	6
4	Firmware version 2.01	7
4.1	What's new	7
4.1.1	Incoming RPS connections	7
4.1.2	B444 signal strength indication	7
4.1.3	B465 cloud default parameters changed	7
4.1.4	APN usage for B442 and B443	7
4.2	What's fixed	7
4.2.1	Stabilization of cell card performance	7
5	Firmware version 2.00	8
5.1	Whats new	8
5.1.1	Updated digital dialer formats	8
5.1.2	Remote Connect Service support	8
5.1.3	Updated Account Setup options	9
5.1.4	B444 support	9
5.1.5	Remote Programming Support	9
5.1.6	Override for Answer RPS over Network	9
5.1.7	Local programming support on upgrade	9
5.1.8	Periodic Test Report	9
5.1.9	Operational improvements	9
5.2	Known issues	9
5.2.1	Modem IIIa2 and GV3 and GV4 control panels	9
5.2.2	Event transmissions	9
5.2.3	Fast receiver supervision times	10
5.2.4	Periodic Test Report Configuration	10
5.2.5	B444 signal strength	10
5.3	Firmware version 2.01	10
5.3.1	What's new	10
5.3.2	What's fixed	11
6	Firmware version 1.00.005	12
6.1	Notable features	12
6.1.1	Updated B440/B441 support	12
6.1.2	Reporting Delay for Low Signal Strength default change	12
6.1.3	No Towers Reporting Delay default	12
6.2	Corrections	12
6.2.1	Cellular reliability	12
6.2.2	Signal strength	12
7	Open source software 3.09	13

1 Introduction

These *Release Notes* are for the B465 with firmware version 2.08.

1.1 Requirements

The B465 supports the following:

Compatible receivers

(Bosch) Conettix D6600 Communications Receiver/Gateway
(Bosch) Conettix D6100IPv6 Communications Receiver/Gateway
(Bosch) Conettix D6100i Communications Receiver/Gateway

Compatible PSTN input reporting formats

Modem II
Modem IIe
Modem IIIa ²
Ademco Contact ID (SIA DC-05) +10 digit account codes
Pulse 3/1, 3/1 Checksum (2300 Hz ACK Tone)
Pulse 3/1, 3/1 Checksum (1400 Hz ACK Tone)
Pulse 4/2 (2300 Hz ACK Tone)
Pulse 4/2 (1400 Hz ACK Tone)
SIA (SIA8, SIA20) 110 and 300 baud

Compatible cellular modules

B440 Conettix Plug-in Cellular Communicator (2G/3G CDMA)
B441 Conettix Plug-in CDMA Cellular Communicator (2G CDMA)
B442 Conettix Plug-in GPRS Cellular Communicator (3G GPRS GSM)
B443 Conettix Plug-in HSPA+ Cellular Communicator (SIM card required) (3G/4G HSPA+ GSM)
B444 Conettix Plug-in 4G VZW LTE Cellular Communicator (4G VZW LTE)

2 Firmware version 2.09

What's new

- *B444-A and B444-V support, page 5*
- *California Security of Connected Devices Act, page 5*

2.1 What's new

This section examines the new features of this firmware version.

2.1.1 B444-A and B444-V support

The system now supports B444-A Plug-in cell module, AT&T LTE and B444-V Plug-in cell module, Verizon LTE.

B444-A/B444-V SIM card activation



Caution!

Activate the B444-A/B444-V SIM card before inserting. Failure to do so might result in failed communications to the control panel/module. Upon first power-up of the B444-A/ B444-V, it might take up to 15 minutes for the activation process to be completed.

2.1.2 California Security of Connected Devices Act

In order to comply with the California Security of Connected Devices Act (TITLE 1.81.26. Security of Connected Devices) this product uses a unique connection password.

The “RPS Passcode” for the initial connection to this product must match the unique Cloud ID of the product.

Ensure your RPS Operator uses the unique Cloud ID that is labeled on the product and included on the card in the box of the product.

3 **Firmware version 2.08**

What's fixed

- *Updates to the bootloader, page 6*
- *Updates to TCP keep alive, page 6*

3.1 **What's fixed**

This section examines the fixed issues of this firmware version.

3.1.1 **Updates to the bootloader**

This firmware release contains updates to improve the performance of the bootloader.

3.1.2 **Updates to TCP keep alive**

This firmware release contains performance improvements related to maintaining connections to the cloud.

4 Firmware version 2.01

What's new

- *Incoming RPS connections, page 7*
- *B444 signal strength indication, page 7*
- *B465 cloud default parameters changed, page 7*
- *APN usage for B442 and B443, page 7*

What's fixed

- *Stabilization of cell card performance, page 7*

4.1 What's new

This section examines the new features of this firmware version.

4.1.1 Incoming RPS connections

In addition to answering incoming calls from RPS using UDP (User Datagram Protocol), incoming calls from RPS using TCP (Transfer Control Protocol) are also supported. RPS version 6.07 is required for this modified connection method.

4.1.2 B444 signal strength indication

The B444 signal strength LED indication has been modified to more accurately represent performance. While LTE tower switching may still occur, their individual signal strength indications are more accurate.

4.1.3 B465 cloud default parameters changed

Cloud connections using Ethernet and/or cellular are now enabled as the default selection to allow for establishing communications.

4.1.4 APN usage for B442 and B443

The B442 and B443 plug-in cellular modules shall attempt connections using APNs in the following order:

1. Primary configured APN
2. gne
3. wyles.com.apn
4. wyles.com.attz

The plug-in cellular module will select and use the most appropriate APN.

If the APN is erroneous, the panel keypads may not display the details of this trouble condition.

4.2 What's fixed

This section examines the fixed issues of this firmware version.

4.2.1 Stabilization of cell card performance

Cell card stability enhancements are included within this firmware release.

5 Firmware version 2.00

What's new

- Updated digital dialer formats, page 8
- Remote Connect Service support
- Updated Account Setup options, page 9
- B444 support, page 9
- Remote Programming Support, page 9
- Override for Answer RPS over Network, page 9
- Local programming support on upgrade, page 9
- Periodic Test Report, page 9
- Operational improvements, page 9

Known issues

- Modem IIIa2 and GV3 and GV4 control panels, page 9
- Event transmissions, page 9
- Fast receiver supervision times, page 10
- Periodic Test Report Configuration, page 10
- B444 signal strength, page 10

5.1 Whats new

This section examines the new features of this firmware version.

5.1.1 Updated digital dialer formats

This firmware update supports the following digital dialer formats:

- Modem II
- Modem IIe
- Modem IIIa²

5.1.2 Remote Connect Service support

Remote Connect Service enables a secure control panel connection to remote programming software (RPS) using Bosch Cloud services. The service allows a secure TLS connection to a control panel without specific port and router settings and without a static IP or DNS.

Notice!

North America only

Remote Connect Services and Bosch Cloud services are currently available in North America only. Before you can utilize Remote connect service or cellular communication for reporting and RPS connections, you need to register for Bosch Installer Service at the Bosch Installer Services Portal, <https://installerservices.boschsecurity.com/>.



Refer to the descriptions below:

- Cloud Remote Connect (Ethernet). Use this option to enable or disable Cloud Remote connection through an Ethernet connection.
- Cloud Remote Connect (Cellular). Use this option to enable or disable Cloud Remote connection through a cellular connection.

Cloud connection not supported on upgrade

Current B465 modules with firmware version 1.00.005 that are upgraded to firmware version 2.00 do not connect to the cloud. Only factory produced modules with valid cloud certificates are able to connect using the cloud.

5.1.3 Updated Account Setup options

The B465 can optionally replace the account number in all received phone events from either phone line with the account number configured in Alternate Account Number. Refer to the descriptions below for new Account Setup prompts:

- Substitute Account Number. Use this option to enable or disable the feature.
- Alternate Account Number. Use this option to set up an alternate account number.

5.1.4 B444 support

This firmware update supports the B444 Conettix Plug-in 4G VZW LTE Cellular Communicator. The use of this module is for the US market only.

5.1.5 Remote Programming Support

RPS Settings. Use this option for remote module configuration when using Remote Programming Software (RPS). The B465 v2.00 supports remote configuration through RPS using USB, Ethernet, and Cellular IP connections. Make sure you use RPS v6.05 or greater.

5.1.6 Override for Answer RPS over Network

When **RPS Settings >> Answer RPS over Network** is set to **Disabled**, RPS cannot establish a remote connection to the B465 over Ethernet or over Cellular IP. Local RPS connection through USB is not affected by this feature. A disabled remote RPS connection can be briefly overridden by opening and closing the on-board tamper input for more than 5 seconds and less than 2 minutes. The override will allow a remote connection from RPS for up to 2 minutes. The override is indicated on the B465 by activating the System Trouble LED.

5.1.7 Local programming support on upgrade

You must update the USB driver (RB_B465.INF v1.3.1000.0) when updating the B465 firmware version from v1.00.005 to v2.00.011 or higher.

The current USB driver is replaced by RBUS1CP.INF v1.2.9500 or newer.

The driver replacement is automatically performed when Remote Programming Software (RPS) v6.05 is installed or done manually. For more information on installing the driver manually, refer to the *Conettix Universal Dual Path Communicator Installation and Operation Manual - USB and TeraTerm* section.

5.1.8 Periodic Test Report

The B465 can send an optional test report containing a general system normal or off-normal status.

5.1.9 Operational improvements

This firmware release contains operational improvements related to the B444 plug-in cellular module.

5.2 Known issues

This section examines the known issues of this firmware version.

5.2.1 Modem IIIa2 and GV3 and GV4 control panels

The digital dialer format Modem IIIa² is not supported on the following control panels:

- D9412GV4/D7412GV4
- D9412GV3/D7412GV3
- D7212GV4/D7212GV3

5.2.2 Event transmissions

The sending of multiple, consecutive, identical events transmit once.

5.2.3 Fast receiver supervision times

Using a fast or high supervision time rate might result in momentary communication troubles from the B465.

5.2.4 Periodic Test Report Configuration

In B465 modules that have firmware version v2.00.002 and greater, the Test Report Interval option can only be configured from the USB Terminal menu. Configuring remotely through RPS is not available in version 6.05. RPS may show an unknown parameter change when the Test Report Interval is not at its default setting of **disabled**.

5.2.5 B444 signal strength

The signal strength LED indicators on the B444 Conettix Plug-in 4G VZW LTE Cellular Communicator module may vary under normal conditions and should be used as a general guideline regarding signal strength and performance. This is due to various factors including:

- Switching frequency bands
- Switching cell towers
- Environmental conditions
- LTE technology factors such as:
 - Modulation scheme
 - Multipath effects
 - Interference

5.3 Firmware version 2.01

What's new

- *Incoming RPS connections, page 10*
- *B444 signal strength indication, page 10*
- *B465 cloud default parameters changed, page 10*
- *APN usage for B442 and B443, page 10*

What's fixed

- *Stabilization of cell card performance, page 11*

5.3.1 What's new

This section examines the new features of this firmware version.

5.3.1.1 Incoming RPS connections

In addition to answering incoming calls from RPS using UDP (User Datagram Protocol), incoming calls from RPS using TCP (Transfer Control Protocol) are also supported. RPS version 6.07 is required for this modified connection method.

5.3.1.2 B444 signal strength indication

The B444 signal strength LED indication has been modified to more accurately represent performance. While LTE tower switching may still occur, their individual signal strength indications are more accurate.

5.3.1.3 B465 cloud default parameters changed

Cloud connections using Ethernet and/or cellular are now enabled as the default selection to allow for establishing communications.

5.3.1.4 APN usage for B442 and B443

The B442 and B443 plug-in cellular modules shall attempt connections using APNs in the following order:

1. Primary configured APN
2. gne
3. wyles.apn
4. wyles.com.attz

The plug-in cellular module will select and use the most appropriate APN.

If the APN is erroneous, the panel keypads may not display the details of this trouble condition.

5.3.2

What's fixed

This section examines the fixed issues of this firmware version.

5.3.2.1

Stabilization of cell card performance

Cell card stability enhancements are included within this firmware release.

6 Firmware version 1.00.005

Notable features

- Updated B440/B441 support
- *Reporting Delay for Low Signal Strength default change, page 12*
- *No Towers Reporting Delay default, page 12*

Corrections

- *Cellular reliability, page 12*
- *Signal strength, page 12*

6.1 Notable features

This section examines the new features of this firmware version.

6.1.1 Updated B440/B441 support

B465 firmware v1.00.005 supports the latest versions of the B440 and B441 plug-in cellular modules (B440 v15.00.026 and B441 v18.02.022). The latest B440/B441 firmware includes updated libraries to maintain Verizon certification, and a correction to show the correct MEID on keypads in the Installer menu.

To use a B440 v15.00.026 or a B441 v18.02.022, the connected B465 must have firmware v1.00.005 or higher.

6.1.2 Reporting Delay for Low Signal Strength default change

The Reporting Delay for Low Signal Strength parameter default value was changed to a state of disabled. The original default value was 1800 seconds. The new default value is zero. When this value is set to zero seconds, this parameter is considered disabled.

6.1.3 No Towers Reporting Delay default

The Reporting Delay for No Towers parameter default value was changed to a state of being disabled. The original default value was 1800 seconds. The new default value is zero. When this value is set to zero seconds, this parameter is considered to be disabled.

6.2 Corrections

This section examines the corrections made in this firmware version.

6.2.1 Cellular reliability

Improved cellular reliability in unstable environments and in situations where other network errors might occur.

6.2.2 Signal strength

Improved cellular signal strength levels by changing the firmware to increase the acceptable levels detected.

7 Open source software 3.09

Bosch includes the open source software modules listed below in the firmware for this control panel. The inclusion of these modules does not limit the Bosch warranty.

Digital Equipment Corporation

Portions Copyright (c) 1993 by Digital Equipment Corporation.

Permission to use, copy, modify, and distribute this software for any purpose with or without fee is hereby granted, provided that the above copyright notice and this permission notice appear in all copies, and that the name of Digital Equipment Corporation not be used in advertising or publicity pertaining to distribution of the document or software without specific, written prior permission.

THE SOFTWARE IS PROVIDED "AS IS" AND DIGITAL EQUIPMENT CORP. DISCLAIMS ALL WARRANTIES WITH REGARD TO THIS SOFTWARE, INCLUDING ALL IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS. IN NO EVENT SHALL DIGITAL EQUIPMENT CORPORATION BE LIABLE FOR ANY SPECIAL, DIRECT, INDIRECT, OR CONSEQUENTIAL DAMAGES OR ANY DAMAGES WHATSOEVER RESULTING FROM LOSS OF USE, DATA OR PROFITS, WHETHER IN AN ACTION OF CONTRACT, NEGLIGENCE OR OTHER TORTIOUS ACTION, ARISING OUT OF OR IN CONNECTION WITH THE USE OR PERFORMANCE OF THIS SOFTWARE.

Digital historical

Copyright 1987 by Digital Equipment Corporation, Maynard, Massachusetts, and the Massachusetts Institute of Technology, Cambridge, Massachusetts.

All Rights Reserved

Permission to use, copy, modify, and distribute this software and its documentation for any purpose and without fee is hereby granted, provided that the above copyright notice appear in all copies and that both that copyright notice and this permission notice appear in supporting documentation, and that the names of Digital or MIT not be used in advertising or publicity pertaining to distribution of the software without specific, written prior permission.

DIGITAL DISCLAIMS ALL WARRANTIES WITH REGARD TO THIS SOFTWARE, INCLUDING ALL IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS, IN NO EVENT SHALL DIGITAL BE LIABLE FOR ANY SPECIAL, INDIRECT OR CONSEQUENTIAL DAMAGES OR ANY DAMAGES WHATSOEVER RESULTING FROM LOSS OF USE, DATA OR PROFITS, WHETHER IN AN ACTION OF CONTRACT, NEGLIGENCE OR OTHER TORTIOUS ACTION, ARISING OUT OF OR IN CONNECTION WITH THE USE OR PERFORMANCE OF THIS SOFTWARE.

OpenSSL License

Copyright (c) 1998-2008 The OpenSSL Project. All rights reserved.

Redistribution and use in source and binary forms, with or without modification, are permitted provided that the following conditions are met:

1. Redistributions of source code must retain the above copyright notice, this list of conditions and the following disclaimer.
2. Redistributions in binary form must reproduce the above copyright notice, this list of conditions and the following disclaimer in the documentation and/or other materials provided with the distribution.
3. All advertising materials mentioning features or use of this software must display the following acknowledgment:

"This product includes software developed by the OpenSSL Project for use in the OpenSSL Toolkit. (<http://www.openssl.org/>)"

4. The names "OpenSSL Toolkit" and "OpenSSL Project" must not be used to endorse or promote products derived from this software without prior written permission. For written permission, please contact openssl-core@openssl.org.

5. Products derived from this software may not be called "OpenSSL" nor may "OpenSSL" appear in their names without prior written permission of the OpenSSL Project.

6. Redistributions of any form whatsoever must retain the following acknowledgment:

"This product includes software developed by the OpenSSL Project for use in the OpenSSL Toolkit (<http://www.openssl.org/>)"

THIS SOFTWARE IS PROVIDED BY THE OpenSSL PROJECT "AS IS" AND ANY EXPRESSED OR IMPLIED WARRANTIES, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE DISCLAIMED. IN NO EVENT SHALL THE OpenSSL PROJECT OR ITS CONTRIBUTORS BE LIABLE FOR ANY DIRECT, INDIRECT, INCIDENTAL, SPECIAL, EXEMPLARY, OR CONSEQUENTIAL DAMAGES (INCLUDING, BUT NOT LIMITED TO, PROCUREMENT OF SUBSTITUTE GOODS OR SERVICES; LOSS OF USE, DATA, OR PROFITS; OR BUSINESS INTERRUPTION) HOWEVER CAUSED AND ON ANY THEORY OF LIABILITY, WHETHER IN CONTRACT, STRICT LIABILITY, OR TORT (INCLUDING NEGLIGENCE OR OTHERWISE) ARISING IN ANY WAY OUT OF THE USE OF THIS SOFTWARE, EVEN IF ADVISED OF THE POSSIBILITY OF SUCH DAMAGE.

This product includes cryptographic software written by Eric Young (eay@cryptsoft.com). This product includes software written by Tim Hudson (tjh@cryptsoft.com).

For more information, refer to the OpenSSL License on www.boschsecurity.com, under Product Catalog.

Regents of the University of California

Copyright (c) 1985, 1993

The Regents of the University of California. All rights reserved.

Redistribution and use in source and binary forms, with or without modification, are permitted provided that the following conditions are met:

1. Redistributions of source code must retain the above copyright notice, this list of conditions and the following disclaimer.
2. Redistributions in binary form must reproduce the above copyright notice, this list of conditions and the following disclaimer in the documentation and/or other materials provided with the distribution.
3. All advertising materials mentioning features or use of this software must display the following acknowledgement: This product includes software developed by the University of California, Berkeley and its contributors.
4. Neither the name of the University nor the names of its contributors may be used to endorse or promote products derived from this software without specific prior written permission.

THIS SOFTWARE IS PROVIDED BY THE REGENTS AND CONTRIBUTORS ``AS IS" AND ANY EXPRESS OR IMPLIED WARRANTIES, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE DISCLAIMED. IN NO EVENT SHALL THE REGENTS OR CONTRIBUTORS BE LIABLE FOR ANY DIRECT, INDIRECT, INCIDENTAL, SPECIAL, EXEMPLARY, OR CONSEQUENTIAL DAMAGES (INCLUDING, BUT NOT LIMITED TO, PROCUREMENT OF SUBSTITUTE GOODS OR SERVICES; LOSS OF USE, DATA, OR PROFITS; OR BUSINESS INTERRUPTION) HOWEVER CAUSED AND ON ANY THEORY OF LIABILITY, WHETHER IN CONTRACT, STRICT LIABILITY, OR TORT (INCLUDING NEGLIGENCE OR OTHERWISE) ARISING IN ANY WAY OUT OF THE USE OF THIS SOFTWARE, EVEN IF ADVISED OF THE POSSIBILITY OF SUCH DAMAGE.

RSA data security

Copyright © 1991-2, RSA Data Security, Inc. Created 1991. All rights reserved.

The "RSA Data Security, Inc. MD5 Message-Digest Algorithm" is included in the control panel firmware.

RSA Data Security, Inc. makes no representations concerning either the merchantability of this software or the suitability of this software for any particular purpose. It is provided "as is" without express or implied warranty of any kind.

Time routines

Copyright © 2002 Michael Ringgaard. All rights reserved.

This software [Time routines] is provided by the copyright holders and contributors "as is" and any express or implied warranties, including, but not limited to, the implied warranties of merchantability and fitness for a particular purpose are disclaimed. In no event shall the copyright owner or contributors be liable for any direct, indirect, incidental, special, exemplary, or consequential damages (including, but not limited to, procurement of substitute goods or services; loss of use, data, or profits; or business interruption) however caused and on any theory of liability, whether in contract, strict liability, or tort (including negligence or otherwise) arising in any way out of the use of this software, even if advised of the possibility of such damage.



Bosch Security Systems B.V.

Torenallee 49

5617 BA Eindhoven

Netherlands

www.boschsecurity.com

© Bosch Security Systems B.V., 2019