## Exit Error Prevention                              November 25, 2008

---

### Issue Severity:

☐ **High:** Act immediately

☒ **Medium:** Bosch Security Systems, Inc. strongly recommends you take the action(s) described below.

☐ **Low:** Advisory

### Products Affected:

- wLSN v3.05 or earlier detectors

- Easy Series Intrusion Control Panels

---

## 1.0  Issue

On wLSN and Easy Series systems with more than eight wLSN devices, some changes in status from off-normal to normal might be ignored during the start of Exit Delay. As a result, if the Easy Series control center is in view of a wLSN motion detector (version 3.05 or earlier), the system might not detect the off-normal to normal status change during Exit Delay, causing an Exit Error.

## 2.0  Resolution

On systems with more than eight wLSN detectors, ensure that any wLSN motion detector (version 3.05 or earlier) that can view the Easy Series control center is configured as one of the first seven devices in the wLSN Hub's device database. Perform the following procedure to accomplish this:

1. At initial discovery, only install batteries in the first seven devices. Make sure that the motion detector to be installed within view of the control center is in this group of seven devices.

2. Run the device discovery process as usual.

3. Walk-test the devices when prompted by the control panel.

4. After the initial seven devices are walk tested, enroll the remaining devices by adding additional devices as usual.

wLSN motion detectors with Version 3.07 firmware or later will not have this issue. Version 3.07 detectors will be available in 2009.

---

**BOSCH**

WPP

TBI 11-14-08 01 wLSN Exit Error Prevention
Technical Bulletin

11/08
wLSN v3.05
Detectors
Page 2 of 2