

### Affects:

- FPA-1000-UL
- FPA-1000-V2
- FPA-1000-LC
- FPA-1000-LT

### 1.0 Issue

Using the on-board Ethernet connection, if the FPA-1000 is programmed to send reports using two different IP addresses to the same receiver, the account will generate a Substitution Error and Communication Fails at the receiver.

### 2.0 Resolution

When using two IP addresses, they must be associated with two different receivers. Sending to a single receiver by two IP addresses is not supported.

