Bosch Security Systems B.V. | Intrusion

Technical Bulletin Fire Drill not following programmed duration on a G Series Panel



Issue severity P		Products affected
	High. Act immediately	► B8512G, B9512G (v3.08.xx, v3.09.xx)
	Medium. Bosch Security Systems strongly recommends you take the action described below.	
\boxtimes	Low. Advisory	

January 08th, 2020

Issue

When using the Fire Drill button on a B925F or B926F keypad, the Fire Drill will not follow the programmed Fire Drill Duration parameter.

Resolution

The Fire Drill will only flash and not keep sounding, to sound the Fire Bell you will need to manually activate the sounders.

This will be resolved in v3.10.xx

Bosch Security Systems B.V.

Torenallee 49 5617 BA Eindhoven Netherlands

www.boschsecurity.com

© Bosch Security Systems B.V., 2020