BOSCH

Technical Bulletin
New Generation POPIT reversed wiring

Issue severity

☐ High. Act immediately

☐ Medium. Bosch Security Systems strongly recommends you take the action described below.

☒ Low. Advisory

Products affected

Name/CTN of product

▶ **D9127T**
▶ **D9127U**

Date

August 20, 2024

Issue

The new generation of POPIT modules will send an "*Open*" status when the bus wiring is reversed. Previous versions of the POPIT module would report "*missing*" if the bus wiring was reversed.

Resolution

Bosch will update the new POPIT in the near future to provide the same indication of "*missing*" for reversed wiring in order to eliminate any potential confusion.

Old POPIT   **New POPIT**

Bosch Security Systems B.V.
Torenallee 49
5617 BA Eindhoven
Netherlands
www.boschsecurity.com
© Bosch Security Systems B.V., 2024