



BOSCH

Invented for life

Release Notes
DIVAR IP System Manager 2.0.0

Date: 15-Mar-2023

Table of Contents

1	Document History	3
2	DIVAR IP System Manager 2.0.0	4
2.1	Installation prerequisites and operation notes DIVAR IP all-in-one 4000/6000	4
2.2	Installation prerequisites and operation notes DIVAR IP all-in-one 7000 (DIP-73xx)	4
2.2.1	DIVAR IP all-in-one 7000 that have DIVAR IP Software Center installed	4
2.2.2	DIVAR IP all-in-one 7000 that have no system software installed	5
2.3	General remarks	5
2.4	Fixed issues	5
2.5	Known limitations and issues	5

1 Document History

Date	Version	Changes
15.03.2023	1.0	Initial Release

2 DIVAR IP System Manager 2.0.0

DIVAR IP System Manager 1.5 application has introduced a central user interface that offers an easy system setup, configuration and application software upgrade for DIVAR IP all-in-one 4000 and DIVAR IP all-in-one 6000 systems. DIVAR IP System Manager 2.0.0 extends these capabilities by adding the **support for DIVAR IP all-in-one 7000 systems (DIP-73xx only)** and doing so replacing and taking over the responsibilities of *DIVAR IP Software Center* (DIP-73 DSC Setup 02.00.0115).

DIVAR IP System Manager 2.0.0 is a web-based application and is easily accessible through the shortcut available on the BVRAdmin user desktop on the DIVAR IP all-in-one 4000/6000/7000 (DIP-73xx).

The ***DIVAR IP - System setup*** page is intended to initially setup and configure the operation mode of the factory default DIVAR IP all-in-one.

The ***Software packages*** page is used to keep the DIVAR IP all-in-one up-to-date and install new application software versions and patches.

Microsoft Windows operating system updates are not part of the intended functionality of DIVAR IP System Manager, standard Windows mechanisms should be used for this purpose.

In version 2.0.0, the *newly introduced Remote Portal connection* page allows the user to optionally register the DIVAR IP to **Remote Portal** to remotely monitor and maintain the video system via the cloud. Please refer to the dedicated Application Note "DIVAR IP all-in-one Remote Portal connectivity" in the product catalog for details as well as the corresponding **Remote System Management** service offering (CTN: CBS-RM-DIPx).

2.1 Installation prerequisites and operation notes DIVAR IP all-in-one 4000/6000

Similar to DIVAR IP System Manager 1.5 installation, a factory default DIVAR IP all-in-one 4000/6000 should be booted up and configured up to the Software Selection screen. To be automatically detected by the Software Selection screen, the DIVAR IP System Manager installation file SystemManager_x64_2.0.0.exe must be located in a folder with the following structure: Drive root\BoschAppliance\ (for example F:\BoschAppliance\ of an attached USB drive). Drive C: and Data drive(s) shall not be used for this purpose.

For further details on installation and operation procedures please refer to the DIVAR IP all-in-one 4000/6000 User manuals.

DIVAR IP all-in-one 4000 and DIVAR IP all-in-one 6000 devices that have DIVAR IP System Manager 1.5 are upgraded to DIVAR IP System Manager 2.0.0 via the **Software packages** page.

2.2 Installation prerequisites and operation notes DIVAR IP all-in-one 7000 (DIP-73xx)

2.2.1 DIVAR IP all-in-one 7000 that have DIVAR IP Software Center installed

To replace DIVAR IP Software Center by DIVAR IP System Manager 2.0.0, the operation mode software must be upgraded as follows:

- If your system is running in BVMS operation mode, upgrade the BVMS version to BVMS 11.1.1.
- If your system is running in VRM operation mode, upgrade the VRM version to VRM 4.03.0025.

For more details about upgrading software with DIVAR IP Software Center, refer to chapter "Upgrading and updating software" in the DIVAR IP all-in-one 7000 User manual.

Run the DIVAR IP System Manager installation file SystemManager_x64_2.0.0.exe as described in more details in the Application Note "DIVAR IP all-in-one Remote Portal connectivity"

Notice: DIVAR IP System Manager 2.0.0 requires an update of the SuperDoctor service. The update will overwrite the existing SuperDoctor settings. You must reapply any specific settings after the update. Make sure to note down your settings before you start the update. After the update, the SuperDoctor password will be reset to the default password *DivaripSD5*. During the DIVAR IP System Manager 2.0.0 installation, the SuperDoctor monitoring service will be deactivated. You must activate it after the installation. Bosch strongly recommends to change the default password immediately after the first sign-in to SuperDoctor.

2.2.2 DIVAR IP all-in-one 7000 that have no system software installed

A factory default DIVAR IP all-in-one 7000 should be booted up and configured up to the Software Selection screen. From there, an installation file *BoschAppliance_Setup_DSC_10.01.0001.exe* must be run. This file is part of the *SystemManager_2.0.0.zip* package. To be automatically detected by the Software Selection screen, the *BoschAppliance_Setup_DSC_10.01.0001.exe* installation file must be located in a folder with the following structure: Drive root\BoschAppliance\ (for example F:\BoschAppliance\ of an attached USB drive).

After the installation of *BoschAppliance_Setup_DSC_10.01.0001.exe* has been successfully completed, the system will restart. After signing in to the administrator account *BVRAdmin*, the Software Selection page is displayed again, showing the DIVAR IP System Manager 2.0.0 installation file *SystemManager_x64_2.0.0.exe*.

Proceed further with the DIVAR IP System Manager 2.0.0 and Operation mode installation as described in more details in the Application Note "DIVAR IP all-in-one Remote Portal connectivity".

2.3 General remarks

When a major application software (e.g. BVMS) is upgraded using the **Software packages** page, dependent components (e.g. for BVMS - VRM, VSG, Transcoder Service) will be also upgraded accordingly.

Downgrade of application software versions is not supported.

DIVAR IP System Manager 2.0.0 is supported on DIVAR IP all-in-one 4000 (DIP-44xx) and DIVAR IP all-in-one 6000 (DIP-64xx) platforms, as well as on DIVAR IP all-in-one 7000 (DIP-73xx) . All other platforms are not supported for this version and the application will not install on them.

2.4 Fixed issues

- DIVAR IP System Manager application version 1.5.0 may become non-responsive while updating the user interface data, if many packages are installed. This issue is fixed in the version 2.0.0. Please make sure you update DIVAR IP System Manager application to version 2.0.0 or higher.

2.5 Known limitations and issues

- DIVAR IP System Manager 2.0.0 can be run only locally on DIVAR IP system itself, it is limited to localhost connection only.
- On the **Software packages** page, DIVAR IP System Manager is represented by two key components: "DIVAR IP System Manager Commander" and "DIVAR IP System Manager Executor". While upgrading, both components shall be upgraded to the same version.
- When mapping network drive to host the upgrade packages, the drive shall be mapped for the Local system account in order to be accessible for the application.
- DIVAR IP System Manager does not check version compatibility of software applications being installed or upgraded. Please refer to the Release notes of corresponding Software packages or individual applications.