



DICENTIS Wireless Conference System



BOSCH

en Release Notes

Table of Contents

1	History	3
2	GUI languages	3
3	Upgrade software.....	3
4	Known issues	4
5	Additional Information (not included in manuals).....	6
5.1	Certified countries	6

1 History

Build	Release	Release Date	Release Comments
1.4.1234	1.4	2017-09-15	<ul style="list-style-type: none"> Added waiting list can be set to 0 Improved the web gui wizard, it enforces the change of the default SSID Added API call for chairperson priority status Improved user experience log in on the DCNM-WDE Fixed, in the web browser the option 'by assignment' works again without DCNM-LSID
1.31.1170	1.31	2017-07-14	<ul style="list-style-type: none"> Improved Wi-Fi channel switching behavior in environments with very high throughput access points from other brands Fixed unsuccessful reset of the secondary WAP Fixed, system remembers the user account after a software update Fixed, dual use devices keep their audio after the system has been powered on via the web browser
1.3.958	1.3	2016-08-01	<ul style="list-style-type: none"> Redundant WAP DCNM-WLIION transportation notice
1.2.825	1.2	2016-05-02	<ul style="list-style-type: none"> Added carrier management Added 25 open microphones Added API Prio call Improved web browser gui Improved Wi-Fi stability Improved channel switching behavior
1.1.742	1.1	2015-11-16	<ul style="list-style-type: none"> Added and changed functionality in RESTful-API: <ul style="list-style-type: none"> - Added individual voting results - Added seats call - Value of {id} changed into {id} as used in the seats call for: <ul style="list-style-type: none"> - GET/speakers/available - GET/speakers - POST/speakers - DELETE/speakers - GET/waiting-list/available - GET/waiting-list - POST/waiting-list - DELETE/waiting-list Added system-info Improved audio during microphone switching
20150717.633	1.0	2015-07-17	<ul style="list-style-type: none"> Initial version

2 GUI languages

	ar	cz	de	en	es	fr	fi	gr	hu	id	it	ja	ko	nl	pl	pt	pt-BR	ru	th	tr	vi	zh-CN
Web pages	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•
DCNM-WDE	•		•	•	•	•	•			•	•	•	•	•	•	•		•	•	•	•	•

3 Upgrade software

Immediately upgrade the software of the DICENTIS wireless conference system to the latest version after subscribing the Wireless Devices to the Wireless Access Point.
 Not upgrading the software might result in undesired system behavior.

To upgrade the software, please follow the instructions below:

First time installation of the system

1. Install the Wireless Access Point and Wireless Devices according to the instructions in the *Installation manual*.
2. Configure the Wireless Access Point via the web browser. Please read the *First use configuration* paragraph in the *Configuration manual*.
3. Subscribe all Wireless Devices to the Wireless Access Point, as described in the *Configuration manual*.

Download the latest software version

4. Download the latest software version at: <https://licensing.boschsecurity.com/software>
5. Extract the zip-file on your local computer.
6. Read the release notes of the latest software version.

Upgrade the system to the latest software version


7. Upgrade the Wireless Devices first, and then
8. Upgrade the Wireless Access Point.

Follow the instructions in the *Configuration manual*.

4 Known issues


Issue:

When switching from Identification mode 'off' to either “at assigned seat” or “at any seat” in the Participants menu, an error shows & the mode doesn't change;




Solution:

To work around this, go to System settings > Seats and remove a checkmark for 'ID' from a single random seat



Go back to the Participants menu and switch to the required Identification mode. No error should occur & the system should now let you make this change:



Once again, go back to System settings > Seats and return the checkmark that you removed previously. The identification should now work correctly and all licenses are now distributed.

Issue:

The PC cannot connect anymore after the wizard is finished.

Solution:

It might happen that the DCNM-WAP changes to a 5GHz channel. Make sure your PC supports 5GHz.

Issue:

After changing the host name, the WAP is not reachable on the new name.

Solution:

Re-start the system.

Issue:

The TV-One CORIOmatrix mini does not react to switching commands from the DCNM-WAP when the webpage of the TV-One Corio is used.

Solution:

Logout from the TV-One CORIOmatrix mini webpage.

Issue:

The Range Test might result in disconnect of the browser application when connected to the DCNM-WAP wirelessly.

Solution:

Start the Range Test from the browser application that is wired connected to the DCNM-WAP.

Issue:

On rare occasions there could be audio artefacts on a device during a discussion (e.g. when replacing a battery). The small artefacts are only audible when listening very carefully. They will disappear after 3-60 seconds.

Solution:

Wait for the artefacts to pass by, system will stabilize itself.

Issue:

The external SDI video switcher does not switch between inputs.

Solution:

Reset the switcher to factory defaults. Set the TCP connection port number to 5000 for the Kramer MV-6. Set the TCP connection port number to 10001 for the TV-One CORIOmatrix mini.

Issue:

When changing the hostname or (de)activating the fixed IP address in the web browser interface, the laptop/PC loses the connection with the DCNM-WAP.

Solution:

Close and then re-open the web browser interface.

5 Additional Information (not included in manuals)

5.1 Certified countries

Although DICENTIS Wireless equipment operates in a license-free band it is subject to local certification regulations. See below the list of countries where the DICENTIS Wireless Conference system is certified. Note that this list is updated regularly.

If you have any questions, or when you encounter a country of interest which is not on the list, please contact your nearest Bosch representative to assist you further.

AX	Åland Islands
AL	Albania
DZ	Algeria
AS	American Samoa
AD	Andorra
AR	Argentina

AU	Australia
AT	Austria
BH	Bahrain
BD	Bangladesh
BY	Belarus
BE	Belgium
BA	Bosnia and Herzegovina
BR	Brazil
BN	Brunei Darussalam
BG	Bulgaria
CM	Cameroon
CA	Canada
KY	Cayman Islands (the)
CL	Chile
CN	China
CX	Christmas Island
CC	Cocos (Keeling) Islands (the)
CO	Colombia
CD	Congo (the Democratic Republic of the)
CK	Cook Islands (the)
CI	Côte d'Ivoire
HR	Croatia
CY	Cyprus
CZ	Czech Republic (the)
DK	Denmark
EG	Egypt
EE	Estonia
ET	Ethiopia
FK	Falkland Islands (the) [Malvinas]
FO	Faroe Islands (the)
FJ	Fiji
FI	Finland
FR	France
GF	French Guiana
PF	French Polynesia
TF	French Southern Territories (the)
GE	Georgia
DE	Germany
GH	Ghana
GR	Greece
GL	Greenland
GP	Guadeloupe
GU	Guam
GG	Guernsey
VA	Holy See (the)
HK	Hong Kong
HU	Hungary
IS	Iceland

IN	India
ID	Indonesia
IE	Ireland
IM	Isle of Man
IT	Italy
JP	Japan
JE	Jersey
KZ	Kazakhstan
KE	Kenya
KR	Korea (the Republic of)
KW	Kuwait
KG	Kyrgyzstan
LV	Latvia
LB	Lebanon
LI	Liechtenstein
LT	Lithuania
LU	Luxembourg
MK	Macedonia (the former Yugoslav Republic of)
MY	Malaysia
MT	Malta
MQ	Martinique
YT	Mayotte
MX	Mexico
MC	Monaco
ME	Montenegro
MA	Morocco
MZ	Mozambique
NL	Netherlands (the)
NZ	New Zealand
NG	Nigeria
NO	Norway
OM	Oman
PE	Peru
PH	Philippines (the)
PL	Poland
PT	Portugal
PR	Puerto Rico
QA	Qatar
RE	Réunion
RO	Romania
RU	Russian Federation (the)
BL	Saint Barthélemy
SH	Saint Helena, Ascension and Tristan da Cunha
MF	Saint Martin (French part)
PM	Saint Pierre and Miquelon
SM	San Marino
SA	Saudi Arabia
RS	Serbia

SG	Singapore
SK	Slovakia
SI	Slovenia
ZA	South Africa
GS	South Georgia and the South Sandwich Islands
ES	Spain
LK	Sri Lanka
SJ	Svalbard and Jan Mayen
SE	Sweden
CH	Switzerland
TW	Taiwan (Province of China)
TJ	Tajikistan
TZ	Tanzania, United Republic of
TH	Thailand
TL	Timor-Leste
TK	Tokelau
TN	Tunisia
TV	Tuvalu
UG	Uganda
UA	Ukraine
AE	United Arab Emirates (the)
GB	United Kingdom of Great Britain and Northern Ireland (the)
UM	United States Minor Outlying Islands (the)
US	United States of America (the)
UY	Uruguay
UZ	Uzbekistan
VU	Vanuatu
VN	Viet Nam
VG	Virgin Islands (British)
VI	Virgin Islands (U.S.)
WF	Wallis and Futuna