



From STDN/PRM	Product Management	Telephone +49 911 93456 0	Nuremberg 29.09.2011
------------------	--------------------	------------------------------	-------------------------

Release Letter

Product:	<i>Monitor Wall</i>
Version:	<i>5.01.0006</i>

This letter contains latest information about the above mentioned software.

1. General

Monitor Wall supports HD video with 720p and 1080p resolutions and the latest Bosch HD cameras.

Existing installations of Monitor Wall can be upgraded to this version.
Applied licenses will still be valid.

Documentation did not change, published version is still applicable.



From STDN/PRM	Product Management	Telephone +49 911 93456 0	Nuremberg 29.09.2011
------------------	--------------------	------------------------------	-------------------------

2. New Features

- Support for HD video with 720p and 1080p resolution.
- Support for latest H.264 and HD BVIP devices.
- Video smoothing capability has been added.
- System parameters can be set remotely via Configuration Manager.

3. Changes

- Integration of MPEG-ActiveX 5.07 for improved HD support.
This MPEG-ActiveX version is dedicated for Monitor Wall 5.01 only and shall not be installed anywhere else. A released MPEG-ActiveX 5.10 is available and should be used instead.

4. Restrictions; Known Issues

- Dual monitors can only be used in span mode configuration.
- Monitor Wall is not fully supported in VIDOS alarm scenarios; scripting via Automation Interface must be used.
- Connections from encoder to Monitor Wall can not directly be disconnected by VIDOS. Work-around is available by connecting to non-existing encoder address.
- Alarm connections from encoders or cameras are not supported by Monitor Wall.
- IP address change by remote does not automatically restart Monitor Wall. Manual restart is required.
- To run Monitor Wall on a Windows 7 system with correct licensing, the below steps must be followed. Otherwise it will run with 30-day demo license only.
 - Install Monitor Wall and Configuration Manager
 - Run Configuration Manager as admin (mandatory for moving license to correct place) and set license (license can only be set if Configuration Manager is running as admin)
 - Run Monitor Wall

Both applications must be run as admin at least once to create the correct link to the valid license file.



From STDN/PRM	Product Management	Telephone +49 911 93456 0	Nuremberg 29.09.2011
------------------	--------------------	------------------------------	-------------------------

5. System Requirements

Hardware	Personal Computer
CPU	Dual Core, 3.0 GHz or better
RAM	min. 2 GB
OS	Windows XP Home/XP Professional SP2/SP3, Windows 7
Graphic Card	Refer to MPEG-ActiveX 5.10
Ethernet Card	100 Mbps
Sound Card	Recommended
Software	DirectX 9.0c Configuration Manager 4.22.0018 or newer
Free Memory (Installation)	200 MB (.NET environment, Monitor Wall, Configuration Manager, MPEG-ActiveX)