

Technical Bulletin

Temporary removal of interconnect cable



BOSCH

Invented for life

Issue severity

- High. Act immediately
- Medium. Bosch Security Systems strongly recommends you take the action described below.
- Low. Advisory

Products affected

- ▶ B208 Octo-input module
- ▶ B308 Octo-output module
- ▶ B450 Conettix Plug-in Communicator Interface
- ▶ B901 Access Control module
- ▶ B and G Series control panels

November 10, 2021

Issue

Due to a component supply issue, the interconnect cable that is normally shipped with these products has been removed. It will be replaced once supplies are available.

Resolution

Customers can continue to connect the affected products by wiring them using the terminal strips.

Once component supply issues have been resolved, the interconnect cable will be shipped with the affected products listed above.

Bosch Security Systems B.V..
Torenallee 49
5617 BA Eindhoven
The Netherlands
www.boschsecurity.com