



Technical Bulletin

New Generation POPIT Missings

Issue severity

- ☐ High. Act immediately
- ☐ Medium. Bosch Security Systems strongly recommends you take the action described below.
- ☒ Low. Advisory

Products affected

Name/CTN of product

- ▶ **D9127T**
- ▶ **D9127U**
- ▶ **B9512G**
- ▶ **B8512G**
- ▶ **D8125**

Date

August 22, 2024

Resolution

Bosch will fix this issue in control panel firmware version 3.15.xxx. Expected to release in Q4, 2024.

Issue


When used on B9512G or B8512G control panels, any changes made from RPS or supporting keypad may result in new generation POPITs connected to a D8125 going *“missing.”*

Points will return on their own (20-30 seconds) but depending on programming, they may need to be cleared or acknowledged.

Old POPIT



New POPIT



Bosch Security Systems B.V.

Torenallee 49

5617 BA Eindhoven

Netherlands

www.boschsecurity.com

© Bosch Security Systems B.V., 2024