

Technical Bulletin

New Generation POPIT noise susceptibility

Issue severity

High. Act immediately

Medium. Bosch Security Systems strongly recommends you take the action described below.

Products affected

Name/CTN of product

- **▶** D9127T-CHI
- ▶ B9512G-CHI
- ▶ B8512G-CHI
- ► B299

Date

October 21, 2024

Issue


Bosch has discovered a performance issue with some D9127T-CHI POPIT modules. This issue is related to devices used on long wired runs and where electrical interference is present. It can cause the device to appear missing or to report using an incorrect address.

This issue ONLY affects D9127T-CHI's shipped starting April 2024 and D9127T shipped starting August 2024.

Affected models can be identified by checking the material number printed on the product packaging. Material numbers F.01U.418.089 (D9127T-CHI) are affected.

Affected units can also be identified by looking for one small capacitor near the center of the printed circuit board (PCB). Previous versions had two stand up capacitors near the side of the PCB and are not affected.

Old POPIT



New POPIT



Resolution

If you are experiencing this issue please try to follow the wiring practices as described below.

- Do not use T-Taps. Each wire run is on its own B299.
- Reduce the length of the wire run.
- Maintain 6 feet of separation between low voltage wiring and electrical motors.
- Maintain 6 feet of separation between low voltage and high voltage electrical cables.
- Always cross high voltage cables at a 90° angle.
- When possible, run low voltage wires inside of conduit with other low voltage only.

Items to avoid

- Generators
- Transformers
- High voltage electrical panels
- Induction heaters
- · Fluorescent light fixtures
- Electrical motors
- Medical equipment
- Factory machines/equipment
- High powered wireless transmitters

Bosch Security Systems B.V.

Torenallee 49
5617 BA Eindhoven
Netherlands

www.boschsecurity.com

© Bosch Security Systems B.V., 2024