

<b>Issue Severity:</b>	<b>Products Affected:</b>
<input type="checkbox"/> <b>High:</b> Act immediately	<ul style="list-style-type: none"><li>• RPS Version 5.5 and earlier</li><li>• D9127 Series POPIT Modules</li><li>• D9412GV2/D7412GV2/D7212GV2 Control Panels</li></ul>
<input type="checkbox"/> <b>Medium:</b> Bosch Security Systems, Inc. strongly recommends you take the action(s) described below.	
<input checked="" type="checkbox"/> <b>Low:</b> Advisory	

**1.0 Issue**

In RPS Version 5.5 and earlier, there is an error in the *D9127 POPIT Hardware Switch Settings* help file topic in all of the GV2 Series Control Panel accounts. The settings for Address 40 show Switch 0 in the **ON** position and Switch 1 in the **OFF** position. If both Switches 0 and 1 are not in the **ON** position for Address 40, the control panel shows Point 40 as missing.

**2.0 Resolution**

Set the DIP switches as shown below for Address 40:

Address	DIP Switch						
	0	1	2	3	4	5	6
40	ON	ON	OFF	OFF	OFF	OFF	OFF

This error will be corrected in a future revision of RPS.

