

# Technical Bulletin

## FLM-325-IM Mini Analog Contact Module



**BOSCH**

Invented for life

### Issue severity

- High. Act immediately
- Medium. Bosch Security Systems strongly recommends you take the action described below.
- Low. Advisory

### Products affected

- ▶ FLM-325-IM
- ▶ FMM-325A
- ▶ FMM-325A-D

**March 30, 2021**

#### Issue

Bosch is issuing an advisory notice that a limited number of FLM-325-IM Mini Analog Contact monitor modules may not indicate a trouble condition for an open EOL resistor when used with the FMM-325A and FMM-325A-D manual pull stations. These modules were manufactured during October 2019 thru October 2020 and distributed.


While we believe the risk that the pull stations will not operate is low, it is important to perform a functional test of the pull stations to ensure their operating condition.

FLM-325-IM includes a label on the side of the terminal block. Those marked with “VER. 2.2” and manufactured from October 2019 to October 2020 are affected. For those that are still in the shipping box are shown as a date code of H109, H119, H129, H010, H020, H030, H040, H050, H060, H070, H080, H090, H100. For date code locations, see the figures on the back of this sheet.

#### Resolution

Please make sure that you inspect these modules during your regular inspections and functional testing

Location of the date code on the terminal block:



Location of the date code on the terminal block:



**Bosch Security Systems LLC**

130 Perinton Parkway

Fairport, New York 14450 USA

**[www.boschsecurity.com](http://www.boschsecurity.com)**

© Bosch Security Systems, LLC., 2021