



From	Product Management	Telephone	Grasbrunn
BT-VS	BT-VS/XSW-SEC	+49 911 93456 0	30-Nov-2021

Release Letter

Product:	<i>DIVAR IP all-in-one 7000 generation 3 Family (DIP-73*)</i>
Version:	<i>DIP-73 Installer for BVMS 10.1.1 MR1</i>

1. General

The Installer combines a number of software components, which are applicable to the above-mentioned product(s). It can be used for initial software installation or as an upgrade of an earlier version, which is already installed on the system.

2. Restrictions; Known Issues

- Access to the administrative BVRAdmin account is necessary in order to install software packages.
- If several BoschAppliance folders are found by the DIVAR IP Software Center application on different drives, the highest version package will be used.

3. New subcomponent software versions

- DIVAR IP Software Center 2.0.113
- BVMS 10.1.1.12
- Video Recording Manager 3.83.0045
- Video Streaming Gateway 7.2.0.44
- Transcoding Service 07.10.0037

4. New Features

BVMS

- New Video Management System features are listed in the Bosch VMS release notes.

VRM

- New VRM features are listed in the VRM release notes.

5. Applied Changes / Bug Fixes

- Installation packages appear in incorrect order in DIVAR IP Software Center 2.0.109 – Fixed
- Patch for BVMS 10.1.1.12 - Security Issue - 350403 is included in the package



From	Product Management	Telephone	Grasbrunn
BT-VS	BT-VS/XSW-SEC	+49 911 93456 0	30-Nov-2021

6. Installation Notes

Initial system setup

DIVAR IP all-in-one 7000 3rd generation products allow for software installation packages to be imported directly during initial system setup. The following steps have to be performed in order to use an updated software installation package on a DIVAR IP all-in-one 7000 3rd generation video management appliance:

- Download and unzip the software installation package (for example, DIP-73 Installer for BVMS 10.1.1 MR1) archive from <http://www.boschsecurity.com>
- Copy the folder structure onto a USB drive, so that BoschAppliance folder is at the root level
Note: make sure that complete folder structure is copied.
- Connect the USB drive to the DIVAR IP all-in-one 7000 system during initial setup, while logging in as BVRAdmin
- Proceed with the system setup until the DIVAR IP Software Center application is opened. Provide BVRAdmin user credentials.
- In the Operation mode selection screens, choose the software version of the package that shall be installed on the system. Click Install button at the bottom of the page.

Depending on the selected Operation mode, the system might require several reboots. After reboot, log-in into the system and provide credentials to the DIVAR IP Software Center application.

Upgrade

- Download and unzip the software installation package (for example, DIP-73 Installer for BVMS 10.1.1 MR1) archive from <http://www.boschsecurity.com>
- Copy the folder structure onto a USB drive, so that BoschAppliance folder is at the root level
Note: make sure that complete folder structure is copied.
- Connect the USB drive to the DIVAR IP all-in-one 7000 system
- Run DIVAR IP Software Center application from the BVMS kiosk mode or from the BVRAdmin user desktop. Provide BVRAdmin user credentials.
- In the Update and Upgrade screen, inspect currently installed and available for upgrade version numbers, press Upgrade button.

Notes:

- During initial boot and installation, the system must be connected to a network.

From BT-VS	Product Management BT-VS/XSW-SEC	Telephone +49 911 93456 0	Grasbrunn 30-Nov-2021
---------------	-------------------------------------	------------------------------	--------------------------

7. History

DIP-73 Installer for BVMS 10.1.1 subcomponent software versions

- DIVAR IP Software Center 2.0.104
- BVMS 10.1.1.12
- Video Recording Manager 3.83.0021
- Video Streaming Gateway 7.2.0.44
- Transcoding Service 07.10.0037