## **UL Installations**

January 29, 2010

Issue Severity:		Product Affected:
	<b>High:</b> Act immediately	DS939 Panoramic Detector
	<b>Medium:</b> Bosch Security Systems, Inc. strongly recommends you take the action(s) described below.	
	Low: Advisory	

## 1.0 Issue

DS939 Panoramic Detectors installed 12 feet (3.7 m) high or greater might not comply with UL catch performance regulations.

## 2.0 Resolution

To comply with UL catch performance regulations, DS939 detectors installed 12 feet (3.7 m) high or greater must have the PIR sensitivity selections pins set to HI, as shown in *Figure 1*.

The DS939 ships from the factory with the PIR sensitivity selection pins set to LO.



